

FIELD INSPECTION REPORT

Project Name:	Mountain Valley Pipeline	Inspector:	Matthew Grant
Inspection Date:	Thursday, October 1, 2020	Project Contact:	Brian Clauto
Spread I: Franklin	MP 265.1-264.9 MP 272.9-272.5 AR FR 315, FR 306.02 ATWS 1466, 356, 356A	Weather:	Dry

ACTIVE STAGE OF CONSTRUCTION: (Check all that apply)

- ☐ Tree Felling
 ☐ Clearing/Grubbing
 ☐ Grading
 ☐ Trenching
 ☐ Stringing/Welding
☐ Lowering/Backfilling
 ☐ Final Grading
 ☐ Temp. Stabilization
 ☐ Perm. Stabilization
 ☒ Dormant

- | | Yes | No | N/A |
|--|-------------------------------------|-------------------------------------|--------------------------|
| 1. Are controls installed and implemented in accordance with the approved erosion and sediment control plan and stormwater management plans? | <input checked="" type="checkbox"/> | <input type="checkbox"/> | <input type="checkbox"/> |
| 2. Are all control measures properly maintained in effective operating condition in accordance with good engineering practices and, where applicable, manufacturer specifications? | <input checked="" type="checkbox"/> | <input type="checkbox"/> | <input type="checkbox"/> |
| 3. Areas of offsite sediment deposition observed? | <input type="checkbox"/> | <input checked="" type="checkbox"/> | <input type="checkbox"/> |

- Comments: Inspected the following resources: S-KL38, S-KL39, S-KL35, W-EF48,W-001,S-A41
- ECD's were in place and appeared to be functioning at crossing.
- S-A41 was noted for corrective action dependent on the Army Corp on 5/4/2020

Routine Maintenance: (72-Hour Deadline from Notification)

- N/A


Ineffective Controls: (24-Hour Deadline from Notification)

- N/A

Recommended Corrective Action: N/A

Deadline: N/A

The recommended corrective action deadline date applies to all conditions noted on this report unless otherwise noted. If listed condition(s) currently constitute non-compliance and/or corrective actions are not completed by the deadline, other enforcement actions may be issued to the entity responsible for ensuring compliance on the above project.

Inspector Signature: _____  _____

Date: Thursday, October 1, 2020

FIELD INSPECTION PHOTO LOG

Project Name: Mountain Valley Pipeline

Date: Thursday, October 1, 2020

- Figure 1: Designated stream S-G36, ECD's are in place.



- Figure 2: Designated stream and wetland crossing S-KL35 & W-EF48, ECD's are in place.



- Figure 3: Near AR FR315 and STWS356 & 356A, ECD's and stabilization is in place.



- Figure 4: Designated stream S-A41, noted for corrective action on 5/4/2020 dependent on the Army Corp.

